


Sensor accessory


4100/5100 AC adapter - domestic



The AC adapter can be utilized for the 4100 and 5100 series of gaussmeters and probes. This adapter is specifically designed for the USA and has 120 V, 60 Hz input. It also contains a DC output of 5 V at 300 mA.



CORD AND CONNECTOR



FEMALE PLUG WITH TIP/CENTER POSITIVE

Contact

OECO
 4607 SE International Way
 Milwaukie, OR 97222
 USA

Tel: +1 (503) 659-5999

www.meggitt.com

www.fwbell.com

www.oeco.com